

25X1A

\*BLACKSHIELD\*

TITLE	DUE		IN	OUT	ACTION	REMARKS
	LCL	Z				
Msn Alert WX Fcst	- 25		X		WX	Filed in 6714 Folder
	1010					
Afld Status	Daily		X		DCO	As of 0900L
	1000					
Tnkr Msn Alert	- 24		X		SAC	# 1
	1110					
Mission Alert	- 24		X		Cmdr DCO DCM	# 2, # 8 is Amendment
	1110					
Mission Plan WX Requirements	- 23		X		WX DCO	# 6
	1210					
Opnl Commo Data	- 22		X		COMMO DCO	# 5
	1310					
EWS Setting	- 22		X		EWS	# 7
	1310					
Tanker/Wx Scout Recall Word	- 22		X		DCO SAC	# 19
	1310					
Mission Alert Confirmation	- 21		X		DCO	# 4
	1410					
Tanker Support Confirmation	- 21		X		SAC	# 3
	1410					
Msn Pln Wx Fcst	- 21		X		WX	# 13
	1410					
Forward Base Wx Fcsts	- 21		X		WX	Filed in 6714 Folder
25X1A	1410					
Inten- tion Alert	- 20		X		DCO	
	1510					
Mission Plan #1	- 18		X		FltPln	# 4
	1710					

OK

\*BLACKSHIELD\*

25X1A

TITLE	DUE		IN	OUT	ACTION	REMARKS
	LCL	Z				
Current Intel	- 18		X		INTEL	#3
	1710					
Msn Pln Wx Fcst	- 17:30		X		WX	#16
	1740					
Forward Base Wx Fcst	- 17:15		X		WX	#17
	1755					
Opnl Capability	Daily NLT 1000Z					
	1900		X		DCM	As of 1700 Local
Mission Plan #2	- 15		X		FltPln	#15 Probably 1004
	2010					
Mission Plan #3	- 15		X		Flt Pln	#9 Probably 1004
	2010					
GO-NO-GO Wx Requirements	NLT 1330Z		X		WX	21
	2230					
Support Acft Stat	Daily NLT 1100Z			X	DCM	As of 1700 Local
	1700					
Tnkr Msn Wx Fcst	- 14		X		SAC WX	#18
	2110					
Tnkr Msn Plan	- 13		X		SAC	#10, #11, 12
	2210					
Camera Pkg Data	-1300		X		DCOMI DCM	(R-81) Exp Number Data ACK Receipt
	2210					
Camera Programming Data	- 12:30		X		FltPln	#14
25X1A	2240					
Support Request	- 12		X		DCO	Probably 1004
	2310					
Activity	- 10		X		COMMO	25X1A
	0110					
NonOpnl Sortie	Daily NLT 2400L		X		DCO	FILED Submitted for next day's Non Operational sorties

COPY

COPY COPY

COPY COPY

COPY COPY

25X1A

\*BLACKSHIELD\*

✓	TITLE	DUE		IN	OUT	ACTION	REMARKS
		LCL	Z				
✓	Special Fuel Test	- 10		X		DCM	(19) (20)
✓		0110					
✓	Forward Base Wx Fcst	- 9		X		WX	21
✓		0210					
✓	Tanker Pre-Sortie Report	- 9		X		SAC	# 7-8-9
✓		0210					
✓	GO-NO-GO Wx Forecast	- 9		X		WX	# 24
✓		0210					
✓	Pre-Sortie Rpt	- 9		X		DCO	(18)
✓		0210					
✓	Haz Wx Advisory	- 7		X		WX	If Adverse Conditions
✓		0410					
✓	Haz Wx Advisory	- 7		X		WX	If Adverse Conditions
✓		0410					
✓	Tanker Msn Sup- port Execution	- 6		X		SAC	# 27
✓		0510					
✓	Emerg Seat Pack	- 5		X		SECURITY	(14)
✓		0610					
✓	Forward Base Wx Forecast	- 3		X		WX	
✓		0810					
✓	Met Watch Obs	- 3		X		WX	
✓	25X1A	0810					
✓	Coord Confirmation	- 3		X		DCO	(25)
✓		0810					
✓	GO-NO-GO Wx Forecast	- 3		X		WX	
✓		0810					
✓	313 AD Coord Confirm	- 2:30		X		DCO	Submit to Hqs 22
✓		0840					

25X1A

\*BLACKSHIELD\*

TITLE	DUE		IN	OUT	ACTION	REMARKS
	LCL	Z				
Wx Scout Rpts	- 2		X		WX	Will be received continuously until AR Areas secured
	0910					
Afld Status	Daily		X		DCO	As of 0900 Local
	1000					
GO-NO-GO	- 1		X		DCO	
	1010					
Take-off	ASAP		X		DCO	
	T.O.					
Abort	As Required		X		DCO	"FLASH"
Mission Landing	ASAP		X		DCO	
Support Canx Msg	ASAP		X		DCO	Give ATA
25X1A	L + ASAP		X		COMMO	
Resume						
Msn Post Indg	L + 2		X		DCO FltPln	
Camera Configuration	L + 3		X		DCM	
Mission Report	L + 3		X		DCO	INFO: CABLE "Eyes Only Cmdr"
Opnl Sortie Rpt	ASAP		X		DCO	25X1A Same as NonOp [REDACTED]
INS Tape	ASAP		X		FltPln	Via 1004 with message back-up
Take Progress	ASAP after Take Departure		X		SECURITY	
Final Field Eval Of INS Data	L + 24		X		DCM	

25X1A

## BLACKSHIRE